

AMENDMENT OF SOLICITATION/MODIFICATION OF CONTRACT		1. CONTRACT ID CODE	PAGE OF PAGES 1 4
2. AMENDMENT/MODIFICATION NO. 0001	3. EFFECTIVE DATE See Block 16C	4. REQUISITION/PURCHASE REQ. NO. MA-PR615-20130397	5. PROJECT NO. (If applicable)
6. ISSUED BY U.S.DOT/ Maritime Administration Atlantic Div. Acquisition Office MAR-380-2 7737 Hampton Blvd Building 19 Suite 300 NORFOLK VA 23505-1204	CODE 00092	7. ADMINISTERED BY (If other than Item 6) U. S. DOT Maritime Administration Atlantic Div. Acquisition Office MAR-380.2 7737 Hampton Blvd Building 19 Suite 300 Norfolk VA 23505-1204	CODE 00092
8. NAME AND ADDRESS OF CONTRACTOR (No., street, county, State and ZIP Code) Crowley Technical Management, Inc. Attn: Patricia Murphy 9487 Regency Square Blvd Jacksonville FL 32225-8126		(x) 9A. AMENDMENT OF SOLICITATION NO.	
CODE 263707071 FACILITY CODE		9B. DATED (SEE ITEM 11)	
		x 10A. MODIFICATION OF CONTRACT/ORDER NO. DTMA8C05004 CTM04A2013016	
		10B. DATED (SEE ITEM 13) 12/20/2012	

11. THIS ITEM ONLY APPLIES TO AMENDMENTS OF SOLICITATIONS

The above numbered solicitation is amended as set forth in Item 14. The hour and date specified for receipt of Offers is extended, is not extended.
Offers must acknowledge receipt of this amendment prior to the hour and date specified in the solicitation or as amended, by one of the following methods: (a) By completing Items 8 and 15, and returning _____ copies of the amendment; (b) By acknowledging receipt of this amendment on each copy of the offer submitted; or (c) By separate letter or telegram which includes a reference to the solicitation and amendment numbers. FAILURE OF YOUR ACKNOWLEDGEMENT TO BE RECEIVED AT THE PLACE DESIGNATED FOR THE RECEIPT OF OFFERS PRIOR TO THE HOUR AND DATE SPECIFIED MAY RESULT IN REJECTION OF YOUR OFFER. If by virtue of this amendment you desire to change an offer already submitted, such change may be made by telegram or letter, provided each telegram or letter makes reference to the solicitation and this amendment, and is received prior to the opening hour and date specified.

12. ACCOUNTING AND APPROPRIATION DATA (If required) Net Increase: \$4,000.00
70XR161710.2013.93140WAS00.1361000000.25432.61006600 / 7013613140WAS0

13. THIS ITEM ONLY APPLIES TO MODIFICATION OF CONTRACTS/ORDERS. IT MODIFIES THE CONTRACT/ORDER NO. AS DESCRIBED IN ITEM 14.

CHECK ONE	A. THIS CHANGE ORDER IS ISSUED PURSUANT TO: (Specify authority) THE CHANGES SET FORTH IN ITEM 14 ARE MADE IN THE CONTRACT ORDER NO. IN ITEM 10A.
	B. THE ABOVE NUMBERED CONTRACT/ORDER IS MODIFIED TO REFLECT THE ADMINISTRATIVE CHANGES (such as changes in paying office, appropriation date, etc.) SET FORTH IN ITEM 14, PURSUANT TO THE AUTHORITY OF FAR 43.103(b).
X	C. THIS SUPPLEMENTAL AGREEMENT IS ENTERED INTO PURSUANT TO AUTHORITY OF: FAR 52.243-2 Changes - Cost-Reimbursement Alt II (Aug 87)
	D. OTHER (Specify type of modification and authority)

E. IMPORTANT: Contractor is not, is required to sign this document and return 1 copies to the issuing office.

14. DESCRIPTION OF AMENDMENT/MODIFICATION (Organized by UCF section headings, including solicitation/contract subject matter where feasible.)

FY13 M&R REPAIRS - CLS-WAS13-1005

The purpose of this modification is to implement a reduction in scope and authorized funding affecting previously authorized Service Requests listed below. This action is being taken preparatory to potential budget cuts that may or may not transpire within the near term. To the degree this reduction ultimately may not be required; a subsequent modification may be issued reinstating these requirements and funding as appropriate.

As a result, there has been a realignment of priority for the SRs and the overall net change to the total contract price results in an INCREASE of \$4,000.00 and new total amount of \$182,000.00.

Continued ...

Except as provided herein, all terms and conditions of the document referenced in Item 9A or 10A, as heretofore changed, remains unchanged and in full force and effect.

15A. NAME AND TITLE OF SIGNER (Type or print)	16A. NAME AND TITLE OF CONTRACTING OFFICER (Type or print) Melinda Simmons-Healy
15B. CONTRACTOR/OFFEROR <i>Marian Mobley</i> (Signature of person authorized to sign)	15C. DATE SIGNED
16B. UNITED STATES OF AMERICA <i>Melinda Simmons-Healy</i> (Signature of Contracting Officer)	16C. DATE SIGNED 01-30-2013

FY13 M&R REPAIRS

The purpose of this project is to accomplish MARAD approved specific work items on the ships approved business plan as identified below. All completed work shall be in compliance with applicable standards as set forth in the Ship Manager contract at C.6.3, Compliance Documents, and subparagraphs thereto, at the time of acceptance.

Ship Manager is authorized to create additional SRs/MRs in NS5 to support this Task Order only if the additional SRs/MRs fall within the original scope of the work items described below on this Task Order. SM shall reference the supplemented original SR/MR # under "Remarks" in each new SR/MR. Furthermore, the Ship Manager is authorized to modify the description in their RFQ and PO documents, resulting from this Task Order, if required to improve their specification as more information becomes available during the Ship Manager's purchasing process - but only if the modified description falls within the scope of work items authorized in this Task Order.

WORK ITEM LIST

Modification No. 1 removes all Work Items below that are in ~~striketthrough~~ format

SR 4727338 - REPLACE THRUSTER INDICATORS - Install new bow and stern thruster indicators to comply with 33 CFR 164.35(n).

SR 4727276 - ENGINE ROOM PIPE INSULATION-REPLACE OIL SOAKED LAGGING AND BLANKETS.

SR 4724412 - ME LOWER CONN ROD BEARING- RECONDITION The contractor shall recondition #1 ME Lower Connecting Rod Bearing. Bearing removed due to surface cracking on load bearing half. The bearing was replaced as per ABS Class Surveyor and SULZER Rep recommendations.

SR 4726500 - BOILER HANDHOLES (BOTTOM)-RESEAT OR REPLACE SEAT – The contractor to repair Seating surface or replace seat and hand hole at lower portion of boiler. Cut out old hand holes (6) and replace with new unit and hydro boiler to ABS satisfaction. There are six hand holes and two manholes. Each will be evaluated and reconditioned to pass hydrostatic testing.

SR 4726275 - CHEMICAL CLEAN CFW SYSTEM WITH FERROCLEAN The contractor shall Ferroclean (or similar) the Central Fresh Water System (approx 22 tons).

~~SR 4725907 - INSTALL STERN TUBE LUBE OIL TRANSFER PUMP - The contractor shall size, procure and install replacement pump with suitable spares availability. Contractors shall state make and model during bid/proposal process. Make and model to be approved by the Chief Engineer for use in stern tube lube oil system.~~

~~SR 4727346 - FLOORING & SHOWER REPAIRS - CREW ROOMS - The contractor to remove old broken tiles from crew rooms as designated by Chief Officer. New tile or equivalent flooring to be installed in the crew rooms, bathrooms and showers as required. Estimate 10 rooms. Approximately 150 sq ft. each room.~~

SR 1108898 - HVAC VENTILATION DUCT REPLACEMENT – The contractor to supply and install approximately forty (40) Hi-Duct/Lo-Duct mixing boxes (manual) for the new HVAC system. Mixing boxes are available locally (Baltimore). Units are available in manual and electrical controls (thermostatic) Each unit shall be designed for easy installation and ductwork change out. The current mixing box shall be taken to the manufacturers facility for sizing and applications (form fit function)

SR 4726122 JACKET WATER COOLER-REGASKET AND CHEMICAL CLEAN – The contractor to provide all labor equipment and materials in order to clean and re-gasket the forty-nine (49) plates from the vessel's Main Engine Jacket Water Plate Cooler. The plates are a mix of Alfa Laval part number 118241-0163 and 118241-0103 titanium plates of approximately 20" x 52" size.

Contractor is to thoroughly clean each plate, both sides; of all deposits and remove all attached and installed gasket materials. Contractor is to properly install new OEM gasket material to each plate to replace the existing gaskets.

Modification No. 1 adds the following Work Item:

4725909 - REPLACE FAULTY TEMPERATURE CONTROLLERS - Replace two faulty Leslie PMC Temperature Controllers with Yokogawa or newer Leslie units in the following locations:

- a. Main Engine Jacket Water Cooler and Evap,
- b. Main Engine Lube Oil, Steam Dump