

AMENDMENT OF SOLICITATION/MODIFICATION OF CONTRACT

1. CONTRACT ID CODE

Page
1 of 22. AMENDMENT/MODIFICATION NO. 0004
3. EFFECTIVE DATE 09/09/2009
4. REQUISITION/PURCHASE REQ. NO. See Lines
5. PROJECT NO. (If applicable)6. ISSUED BY DOT/Maritime Administration, DGO Acquisition
500 Poydras Street, Room 1223
New Orleans, LA 70130-3394
CODE 00093
7. ADMINISTERED BY (If other than Item 6) CODE

8. NAME AND ADDRESS OF CONTRACTOR (No., street, county, State and Zip Code)

Crowley Liner Services, Inc.
9487 Regency Square Blvd,
Jacksonville, FL 32225-8126

9A. AMENDMENT OF SOLICITATION NO.

9B. DATED (SEE ITEM 11)

(X) 10A. MODIFICATION OF CONTRACT/ORDER
NO. DTMA8C05008 / CLS08C09015(X) 10B. DATED (SEE ITEM 13)
12/04/2008

CODE * FACILITY CODE

11. THIS ITEM ONLY APPLIES TO AMENDMENTS OF SOLICITATIONS The above numbered solicitation is amended as set forth in Item 14. The hour and date specified for receipt of Offers is extended, is not extended.

Offers must acknowledge receipt of this amendment prior to the hour and date specified in the solicitation or as amended, by one of the following methods:

(a) By completing Items 8 and 15, and returning _____ copies of the amendment; (b) By acknowledging receipt of this amendment on each copy of the offer submitted; or (c) By separate letter or telegram which includes a reference to the solicitation and amendment numbers. FAILURE OF YOUR ACKNOWLEDGMENT TO BE RECEIVED AT THE PLACE DESIGNATED FOR THE RECEIPT OF OFFERS PRIOR TO THE HOUR AND DATE SPECIFIED MAY RESULT IN REJECTION OF YOUR OFFER. If by virtue of this amendment you desire to change an offer already submitted, such change may be made by telegram or letter, provided each telegram or letter makes reference to the solicitation and this amendment, and is received prior to the opening hour and date specified.

12. ACCOUNTING AND APPROPRIATION DATA (If required)

2009 - - X4303 - RRF - 9 - 3240 - - TEX00 - - 70 - 096132 - 40 - TEX0 - 25432 - 6100 - 6600 -

13. THIS ITEM ONLY APPLIES TO MODIFICATION OF CONTRACTS/ORDERS.

IT MODIFIES THE CONTRACT/ORDER NO. AS DESCRIBED IN ITEM 14.

CHECK ONE
 A. THIS CHANGE ORDER IS ISSUED PURSUANT TO: (Specify authority) THE CHANGES SET FORTH IN ITEM 14 ARE MADE IN THE CONTRACT ORDER NO. IN ITEM 10A. B. THE ABOVE NUMBERED CONTRACT/ORDER IS MODIFIED TO REFLECT THE ADMINISTRATIVE CHANGES (such as changes in paying office, appropriation date, etc.) SET FORTH IN ITEM 14, PURSUANT TO THE AUTHORITY OF FAR 43.103(b). C. THIS SUPPLEMENTAL AGREEMENT IS ENTERED INTO PURSUANT TO AUTHORITY OF: D. OTHER (Specify type of modification and authority)
G.11, Task Order-ReimbursableE. IMPORTANT: Contractor is not, is required to sign this document and return _____ copies to the issuing office.**14. DESCRIPTION OF AMENDMENT/MODIFICATION (Organized by UCF section headings, including solicitation/contract subject matter where feasible.)**

The purpose of this modification is to:

- a) Remove SR 1104512, Kingpost Steel Repairs, and,
-
- b) Add SR 1104827, Lifeboat Repair.

There is no change to the task order total value as a result of this modification.0

Except as provided herein, all terms and conditions of the document referenced in Item 9A or 10A, as heretofore changed, remains unchanged and in full force and effect.

15A. NAME AND TITLE OF SIGNER (Type or print)

16A. NAME AND TITLE OF CONTRACTING OFFICER (Type or print)
Marie Casse

15B. CONTRACTOR/OFFEROR

15C. DATE SIGNED

16B. United States of

16C. DATE SIGNED

(Signature of person authorized to sign)

BY 
(Signature of Contracting Officer)

09/09/2009

Line Item Summary	Document Number CLS08C09015/0004	Title TEX-FY09 M&R REPAIRS A	Page 2 of 2
--------------------------	--	--	-----------------------

Total Funding: \$767,051.00

FYs	Fund	Budget Org	Sub	Object Class	Sub	Program	Cost Org	Sub	Proj/Job No.	Sub	Reporting Category
Division		Closed FYs		Cancelled Fund							

Line Item Number	Description	Delivery Date (Start date to End date)	Quantity	Unit of Issue	Unit Price	Total Cost
------------------	-------------	---	----------	---------------	------------	------------

0001	CLIN 0402AE-Cost reimbursable items (see Attachment J-9) individually funded via task order Change in Extended Description This modification is issued to remove SR1104512 and add SR1104827. (See Revision to Work Item List below). Base year 4, Ship group 8, Ship 2 (CAPE TEXAS) FY09 M&R REPAIRS A Project Number: CLS-TEX09-1005A Account Number: 010-005 The purpose of this project is to accomplish MARAD approved specific work items on the ship's approved business plan as identified below. All completed work shall be in compliance with applicable standards as set forth in the Ship Manager contract at C.6.3, Compliance Documents, and subparagraphs thereto, at the time of acceptance.	(12/01/2008 to 09/30/2009)	0.00	LOT	\$0.00	\$0.00
------	--	----------------------------	------	-----	--------	--------

Ref Req No: PRCR0900105

Previous Total: \$767,051.00
Modification Total: \$0.00
Grand Total: \$767,051.00
(Includes Discounts)

CAPE TEXAS

FY09 M&R REPAIRS A

Project Number: CLS-TEX09-1005A

Account Number: 010-005

Revised Work Item List:

Remove SR 1104512 Aft Kingpost Steel Repairs —

~~The upper horizontal stiffeners/tableplates in both the port and stbd aft kingposts have no drains, and since these kingposts are used as ventilation shafts for the cargo decks, water has come in thru the vent coamings over the years, collected on the tableplates and wasted away all the adjoining structure per the attached pictures. This is an important concern because this structural reinforcement is immediately below the sheaves that lift the stern ramp and hence they must support that load.~~

Add SR 1104827, Lifeboat Repair - Furnish labor, equipment, materials and transportation to perform a complete inspection and refurbishment on the vessels Starboard Lifeboat.

All work to be completed in accordance with applicable ABS/USCG Regulations.

R 1103844 Main Engine Turbocharger Inspection

Furnish services of MAN representative to inspect and provide report on MAN 52/55 engine components removed for inspection by owner and to assist as necessary with re-assembly.

SR 1103845 Air Cooler Cleaning

Furnish labor, equipment and materials to clean the vessels Auxiliary Diesel Engine Air Coolers and one (1) spare cartridge for main engines.

SR 1103846 Main Engine Pneumatics

Furnish services of qualified MAN-authorized representatives to perform comprehensive inspection, cleaning and maintenance on the vessels MAN 52/55 Pneumatics Systems.

SR# 1100472 – Spare Steering Pump

The intent of this SR is to procure a complete steering pump as critical spare.

SR# 1100471 – Spare Central Fresh Water Cooling Water Pump Motor

The intent of this SR is to procure a new Central Cooling Water pump motor as critical spare.

SR# 1101970 – Calibration of Gauges

The intent of this SR is to procure and install new gauges and thermometers to replace those found damaged or missing per provided list.

SR# 1103454 – Port and Starboard Anchor Windlass Brake Pad Renewal and Miscellaneous Repairs

The intent of this SR is to renew brake band lining on (2) anchor windlass unit brakes and complete other miscellaneous other repairs.

SR# 1100562 – Spare Cargo Gear Wires

The intent of this SR is to procure and store aboard vessel one set of cargo gear wires as critical spares.

SR# 1100235 – Repair of Insulation

The intent of this SR is to accomplish the repair/renewal/abatement of various sections of deteriorated insulation in the engine room as per provided list.

SR# 1100238 – Coating Maintenance

The intent of this SR is clean, prepare and coat the cargo tie downs on the weather deck and both hydraulic elevator pits.

SR# 1101971 – Ballast Valve Repairs

The intent of this SR is to disconnect and remove, clean, overhaul and reinstall various ballast valves in double bottom tanks.

SR# 1102927 – Power Conservation Modifications

The intent of this SR is to install power monitoring equipment and to procure and replace existing incandescent light bulbs with compact fluorescent light bulbs.

SR# 1100220 – Piping Repairs

The intent of this SR is to remove and renew various size sections of deteriorated piping and fittings, throughout the vessel, as per provided list.

SR# 1100223 – Hydraulic Repairs

The intent of this item is to renew large quantity of hydraulic hoses on Stern Ramp, Side port Door, Ramps, Elevators, machinery and/or other hydraulic equipment, due on date per provided list, and perform minor hydraulic repairs as required.

SR# 1100229 – Renewal of HVAC Ducting

The intent of this SR is to crop and renew deteriorated engine room supply air ducting with new stainless steel ducting.

SR# 1100226 – Automation Repairs (2nd Qtr)

The intent of this SR is to provide services of a qualified electrician to wire up the galley equipment so the equipment is secured when the galley fire extinguishing system is activated.

SR# 1102929 – Air Supply Duct Repairs

The intent of this SR is to crop and renew wasted sections of the ships Inlet air supply ducting, in its entirety, from the Air Handler room on B-Deck to the bridge deck. Crew OT will be required to support work effort.

SR# 1103019 – HVAC Recirculation Damper Installation

The intent of this SR is to install new HVAC recirculation duct damper and USCG-approved fire damper, on each accommodation deck, in the vessels new air supply duct as per provided ABS approved drawings.

SR# 1100141 – Inspect Auxiliary Diesel Engines

The intent of this SR is to provide necessary industrial assistance and original equipment manufacturers (OEM) replacement parts, as necessary, to open and inspect for Regulatory Credit the vessels Auxiliary Diesel Engines. Crew OT will be required to support work effort.

SR# 1100247 – Inspect Main Engines

The intent of this SR is to provide necessary industrial assistance and original equipment manufacturers (OEM) replacement parts, as necessary, to open and inspect for Regulatory Credit the vessels Main Engines. Crew OT will be required to support work effort.

SR# 1103012 – Automation Repairs (3rd Qtr)

The intent of this SR is to provide services of a qualified automation technician to install new fire alarms in various spaces where not currently monitored.

#####